

Asbestos Removal Area Clearance Certificate


SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-104

PAYNTERS

Rockhampton Girls Grammar Denham Street Rockhampton 4700

09/10/2021

Client Details	
Client name:	Colin Balderson
Client contact:	Mobile 0437 003 316
Removal Work Details	
Date:	09/10/2021
Address:	201-104- PAYNTERS - Rockhampton Girls Grammar Denham Street Rockhampton 4700
Specific work area:	Internal of Building 17
Scope:	Removal of two asbestos sheets around serving roller shutter to the south/east corner of building approximately 4m2
Name of supervisor:	Lloyd Kiel
Inspection Details	
Time:	10:00am
Date:	09/10/2021
Paperwork	
ARCP/SWMS satisfactory:	Yes
Notification given:	Yes
Work consistent with relevant documentation:	Yes
Non/Friable ACM	
First pass dust inspection satisfactory:	Yes
Final visual inspection satisfactory:	Yes
Specific areas inspected:	All horizontal surfaces in the specified work area
Comments:	No signs of visible dust or debris found at time of inspection
Air monitoring conducted:	WIP
Results:	All samples <0.01fb/mL; concentration of respirable airborne fibres consistent with normal ambient air conditions
Date:	09/10/2021
Declaration	
I declare that: - asbestos decontamination work area are free from any visible asbestos; - the transit route and waste routes are free from any asbestos; - Section 1 & 2 ceiling void.	
Signature:	
Name:	Sylvia Kaiki
Date:	09/10/2021
License Number:	2317154

Photographs

Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-104

PAYNTERS


Rockhampton Girls Grammar Denham Street Rockhampton 4700

09/10/2021

Photo: 1 Pre- Removal of wall sheets around roller door



Photo: 2 Pre- Removal of wall sheets around roller door



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-104

PAYNTERS

Rockhampton Girls Grammar Denham Street Rockhampton 4700

09/10/2021

Photo: 3 Post- Removal of wall sheets around roller door



Photo: 4 Post- Removal of wall sheets around roller door



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-104

PAYNTERS

Rockhampton Girls Grammar Denham Street Rockhampton 4700

09/10/2021

.

.