

Asbestos Removal Area Clearance Certificate


SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-095

PAYNTERS

Rockhampton Girls Grammar Denham Street Rockhampton 4700

11/09/2021

Client Details	
Client name:	Colin Balderson
Client contact:	Mobile 0437 003 316
Removal Work Details	
Date:	11/09/2021
Address:	201-95- PAYNTERS - Rockhampton Girls Grammar Denham Street Rockhampton 4700
Specific work area:	Ceiling void to Patterson Building Sections A & B
Scope:	Full decontamination of ceiling void to two sections A & B, approximately 350m2
Name of supervisor:	Zack Smith
Inspection Details	
Time:	15:00pm
Date:	11/09/2021
Paperwork	
ARCP/SWMS satisfactory:	Yes
Notification given:	Yes
Work consistent with relevant documentation:	Yes
Non/Friable ACM	
First pass dust inspection satisfactory:	Yes
Final visual inspection satisfactory:	Yes
Specific areas inspected:	All horizontal surfaces in the specified work area
Comments:	No signs of visible dust or debris found at time of inspection
Air monitoring conducted:	WIP
Results:	All samples <0.01fb/mL; concentration of respirable airborne fibres consistent with normal ambient air conditions
Date:	11/09/2021
Declaration	
I declare that: - asbestos decontamination work area are free from any visible asbestos; - the transit route and waste routes are free from any asbestos; - Section 1 & 2 ceiling void.	
Signature:	 Date: 11/9/2021
Name:	Sylvia Kaiki License Number: 2317154

Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-095

PAYNTERS

Rockhampton Girls Grammar Denham Street Rockhampton 4700

11/09/2021

Photographs

Photo: 1 Pre-Decontamination to ceiling void.



Photo: 2 Post-Decontamination to ceiling void.



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-095

PAYNTERS

Rockhampton Girls Grammar Denham Street Rockhampton 4700

11/09/2021

Photo: 3 Post-Decontamination to ceiling void.



Photo: 4 Post-Decontamination to ceiling void.



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-095

PAYNTERS

Rockhampton Girls Grammar Denham Street Rockhampton 4700

11/09/2021

.

.