Air Monitoring Fieldsheet

SLS ENV PTY LTD

Client	Paynters	**Job Number**	201-112-001	**Sample Date**	20/11/2021
Contact	Colin Balderson – 0437 003 316	**Site**	COA -201-112-PAYNTERS-Rockhampton Girls Gramma Patterson Building	**Sampled By**	Sylvia Kaiki
			Removal of asbestos upper wall sheeting to partition wall, approximately 1.5m2	**Sample Type**	Exposure /Control
				Analysed By:	Sylvia Kaiki
Phone				**Analysis Date:**	20/11/2021

3	Phase	Location	Cassette	Pump	Airflow On (mL/min)	Airflow Off (mL/min)	Airflow Avg (mL/min)	Time On	Time Off	Time (mins)	Volume (L)	Fields	Fibres	Conc. (fb/mL)
SLS001	WIP/C	North elevation of removal area on wall. .	SLS001	SLS01	2.0	2.0	2.0	06:30	10:30	240	480	100	0	<0.01
SLS002	WIP/C	South elevation of removal area on cupboard	SLS002	SLS02	2.0	2.0	2.0	076:31	10:31	240	480	100	0	<0.01
SLS003	WIP/C	West elevation of removal area on wall	SLS003	SLS03	2.0	2.0	2.0	06:32	10:32	240	480	100	0	<0.01
SLS004	BL		SLSOO4									100	0	<0.01