

Asbestos Removal Area Clearance Certificate


SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-112

PAYNTERS-

Rockhampton Girls Gramma Patterson Building

20/11/2021

Client Details	
Client name:	PAYNTERS
Client contact:	Colin Balderson 0437 003 316
Removal Work Details	
Date:	20/11/2021
Address:	201-112-PAYNTERS-Rockhampton Girls Gramma Patterson Building
Specific work area:	East Veranda.
Scope:	Removal of asbestos wall sheeting to upper of partition wall, approximately 4m2
Name of supervisor:	Lloyd Kiel 0466 610 799
Inspection Details	
Time:	10:30am
Date:	20/11/2021
Paperwork	
ARCP/SWMS satisfactory:	Yes
Notification given:	Yes
Work consistent with relevant documentation:	Yes
Non/Friable ACM	
First pass dust inspection satisfactory:	Yes
Final visual inspection satisfactory:	Yes
Specific areas inspected:	All horizontal surfaces in the specified work area
Comments:	No signs of visible dust or debris found at time of inspection
Air monitoring conducted:	WIP
Results:	All samples <0.01fb/mL; concentration of respirable airborne fibres consistent with normal ambient air conditions
Date:	20/11/2021
Declaration	
I declare that: - asbestos decontamination work area are free from any visible asbestos; - the transit route and waste routes are free from any asbestos;	
Signature:	
Name:	Sylvia Kaiki
Date:	20/11/2021
License Number:	2317154

Photographs

Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-112

PAYNTERS-

Rockhampton Girls Gramma Patterson Building

20/11/2021

Photo: 1 Pre-removal of Asbestos wall sheeting to Patterson building exclusion zone.



Photo: 2 Pre-removal of Asbestos wall sheeting upper



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-112

PAYNTERS-

Rockhampton Girls Gramma Patterson Building

20/11/2021

Photo: 3 Pre-removal of Asbestos wall sheeting upper



Photo: 4 Post- removal of Asbestos wall sheeting upper



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-112

PAYNTERS-

Rockhampton Girls Gramma Patterson Building

20/11/2021

Photo: 5 Post- removal of Asbestos wall sheeting upper



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-112

PAYNTERS-

Rockhampton Girls Grammar Patterson Building

20/11/2021