


Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201;014

Rockhampton Girls Grammar Cnr Denham & Agnes Streets Rockhampton QLD 4700—
23/04/2021

Client Details	
Client name:	Rockhampton Girls Grammar
Client contact:	Kasey Mitchell 07 4930 0901
Removal Work Details	
Date:	23/04/2021
Address:	Rockhampton Girls Grammar Cnr Denham & Agnes Streets Rockhampton QLD 4700
Specific work area:	Swimming Pool Change Room
Scope:	Removal of external asbestos soffit sheets all elevations of building, approximately 20m2 Removal of internal asbestos wall sheets to toilet block, located on the North/West corner of building, approximately 10m2 Removal of internal Asbestos ceiling to change room, Approximately 30m2 Removal of Asbestos wall sheets to shower area, Approximately 4m2.
Name of supervisor:	Richard Shepherd
Inspection Details	
Time:	15:00pm
Date:	23/04/2021
Paperwork	
ARCP/SWMS satisfactory:	Yes
Notification given:	Yes
Work consistent with relevant documentation:	Yes
Non/Friable ACM	
First pass dust inspection satisfactory:	Yes
Final visual inspection satisfactory:	Yes
Specific areas inspected:	All horizontal surfaces in the specified work area
Comments:	No signs of visible dust or debris found at time of inspection
Air monitoring conducted:	WIP / Clearance
Results:	All samples <0.01fb/mL; concentration of respirable airborne fibres consistent with normal ambient air conditions
Date:	23/04/2021
Declaration	
I declare that: • asbestos removal work area are free from any visible asbestos; • the transit route and waste routes are free from any asbestos; and • all asbestos in the scope of the work has been removed. • Note One infill wall sheet remains to roof step up on west elevation, approximately 2m2	
Signature:	
Name: Sylvia Kaiki	Date: 23/04/2021
License Number:	2317154

Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201;014

Rockhampton Girls Grammar Cnr Denham & Agnes Streets Rockhampton QLD 4700—
23/04/2021

Photographs

Photo ;1: Front of Building




Photo ;2: Post removal soffits sheets



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201;014

Rockhampton Girls Grammar Cnr Denham & Agnes Streets Rockhampton QLD 4700–
23/04/2021

Photo :3: Post removal of soffit sheets.



Photo :4: Post removal of wall sheets to toilet.



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201;014

Rockhampton Girls Grammar Cnr Denham & Agnes Streets Rockhampton QLD 4700–
23/04/2021

Photo :5: Post removal of wall sheets to shower.




Photo :6: Post removal of wall sheets to shower




Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201;014

Rockhampton Girls Grammar Cnr Denham & Agnes Streets Rockhampton QLD 4700—
23/04/2021

Photo :7: Post removal of ceiling sheets change room.



SLS ENV PTY LTD

[illegible]

SLS ENV PTY LTD

[illegible]

