

Asbestos Removal Area Clearance Certificate


SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-089

PAYNTERS

Rockhampton Girls Grammar 4700

28/08/2021

Client Details	
Client name:	WOLLEMI FLEXI
Client contact:	Colin Balderson 0437 003 316
Removal Work Details	
Date:	28-29/08/2021
Address:	201-89- PAYNTERS - Rockhampton Girls Grammar 4700
Specific work area:	Building 17
Scope:	Removal of ACM ceiling sheets Approximately 120m2 Removal of two wall sheets external south/east corner, approximately 4m2 Removal of two wall sheets internal south/east corner, approximately 4m2
Name of supervisor:	Kane Williams
Inspection Details	
Time:	14:00pm
Date:	28/08/2021
Paperwork	
ARCP/SWMS satisfactory:	Yes
Notification given:	Yes
Work consistent with relevant documentation:	Yes
Non/Friable ACM	
First pass dust inspection satisfactory:	Yes
Final visual inspection satisfactory:	Yes
Specific areas inspected:	All horizontal surfaces in the specified work area
Comments:	No signs of visible dust or debris found at time of inspection
Air monitoring conducted:	WIP
Results:	All samples <0.01fb/mL; concentration of respirable airborne fibres consistent with normal ambient air conditions
Date:	28/08/2021
Declaration	
I declare that: - asbestos decontamination work area are free from any visible asbestos; - the transit route and waste routes are free from any asbestos;	
Signature:	
Name:	Sylvia Kaiki
Date:	28/08/2021
License Number:	2317154

Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-089

PAYNTERS

Rockhampton Girls Grammar 4700

28/08/2021

Photographs

Photo: 1 Pre removal of asbestos ceiling sheets.



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-089
PAYNTERS
Rockhampton Girls Grammar 4700

28/08/2021

Photo: 2 Pre removal of asbestos ceiling sheets.



Photo: 3 Pre removal of asbestos ceiling sheets.



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-089
PAYNTERS
Rockhampton Girls Grammar 4700

28/08/2021

Photo: 4 Post removal of asbestos ceiling sheets.



Photo: 5 Post removal of asbestos ceiling sheets.



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-089
PAYNTERS
Rockhampton Girls Grammar 4700

28/08/2021

Photo: 6 Post removal of asbestos ceiling sheets.



Asbestos Removal Area Clearance Certificate

SLS Environmental Australia Pty Ltd

Clearance Certificate No; 201-089

PAYNTERS

Rockhampton Girls Grammar 4700

28/08/2021

.

.