

VISUAL CLEARANCE CERTIFICATE

1. Date of Inspection: 7 July 2026

2. Client: Rockhampton Girls Grammar School - Kasey Mitchell

3. Client Contact Details: Kasey - 0427 414 819

4. Address where asbestos cleaning and air monitoring was undertaken:

*Rockhampton Girls Grammar School - Corner Denham and Agnes Streets Rockhampton
4700 - Grant Art Room*

5. Date & Time of Clearance Inspection:

Date: 8/07/2026

Time: 2PM

6. Notes:

The camera I took clearance photos with had an issue and I could only find the photo attached.

7. Do you have a copy of the Notification Form (Form 65)?

Yes

8. What type of ACM was removed

Non- friable

8. Was air monitoring required?

No

If yes are the results available from a NATA Laboratory?

N/A


9. Was any ACM visually identified in the work area?

NO

10. Can the area be reoccupied?

YES

Next Page



DECLARATION

11. After a visual inspection and background air monitoring of the Prep Room at:

*Rockhampton Girls Grammar School - Corner Denham and Agnes Streets Rockhampton
4700 - Grant Art Room*

12. Description of removal: removal of asbestos floor tiles. Approximately 135 square metres in total

I declare that both of the removal area is free from any visible asbestos containing materials and the route to the lined tipper is free from any visual asbestos.

Signature of Competent Person

Adrian Price

Name of Competent Person

13. Date: 8 July 2026

***Rockhampton Girls Grammar School - Corner Denham and Agnes Streets Rockhampton
4700 - Grant Art Room***

